

Post Office Box 968 Santa Fe, New Mexico 87504-0968

ENVIRONMENTAL IMPROVEMENT DIVISION

Michael J. Burkhart Director

GARREY CARRUTHERS

July 8, 1988

Mark Satterwhite, 6H-SS New Mexico State Coordinator US EPA 1445 Ross Avenue Dallas, Texas 75202-2733

Dear Mark:

Enclosed for EPA review are the Site Discovery and Preliminary Assessment for UNC San Mateo mine. UNC San Mateo mine is an unreclaimed, inactive, uranium mine with large spoils piles containing high concentrations of selenium, molybdenum, radium-226, and gross-alpha activity. Releases of contaminants to drainage sediment and surface been documented during previous NMEID investigations. The NMEID investigation also documented contamination of ground water down-gradient of the site; however, it has not yet been determined if this contamination is attributable to UNC San Mateo mine.

Preliminary ranking of the site using the 1982 HRS suggests that NPL listing would be likely if either a release to ground water or a release by air transport were observed and documented. Due to the unreclaimed condition of the site either of these are possible.

We recommend that a site investigation be conducted to determine if the site is contributing contaminants to ground water or if contaminants are being released from the site by air transport.

If you have any questions regarding this site or our evaluation please call me at (505) 827-2898.

Sincere/ly,

Steve J. Cary, Program Manager Superfund Section Hazardous Waste Bureau

SC:RM:dlr

Enclosures

SUPERFUND FILE

MAR 26 1992

HEUHUANIZE" 12230755 15